



NO.	DATE	DESCRIPTION

PORT EWEN FIRE HOUSE  
 PORT EWEN  
 FIRE DEPARTMENT  
 ULSTER, NEW YORK



MASONRY DETAILS




4 TYPICAL BOND BEAM LOCATIONS  
 S400 N.T.S



8 MASONRY LINTEL  
 S400 N.T.S




7 TYPICAL STRUCTURAL BOND BEAM IN CMU WALLS  
 S400 N.T.S




3 CMU WALL CONTROL JOINT  
 S400 N.T.S

3 CMU WALL CONTROL JOINT  
 S400 N.T.S




2 CMU CORNER OR TEE - PLAN VIEW  
 S400 N.T.S




6 TYPICAL BOND BEAM CONTROL JOINT DETAIL  
 S400 N.T.S


6 TYPICAL BOND BEAM CONTROL JOINT DETAIL  
 S400 N.T.S




5 CMU WALL PIER  
 S400 N.T.S



1 CMU WALL WITH REINFORCEMENT AT CENTER LINE - PLAN VIEW  
 S400 N.T.S




11 PERIMETER ANGLE AT MASONRY WALL  
 S400 N.T.S




10 TYPICAL REINFORCEMENT AROUND WALL OPENINGS  
 S400 N.T.S


10 TYPICAL REINFORCEMENT AROUND WALL OPENINGS  
 S400 N.T.S




13 EMBED DETAILS  
 S400 N.T.S



13 EMBED DETAILS  
 S400 N.T.S



12 SLAB EDGE AT STAIR  
 S400 N.T.S



9 TYPICAL BEAM BEARING DETAIL @ NEW WALL  
 S400 N.T.S

**BID SET**