

April 14, 2023

Ms. Annie Pau Asbestos EHS PM JLL/JPMorgan Chase Account 4 Metrotech Center, 18th Floor Brooklyn, NY 11245

Re: AD-2023-1QACM-Limited Asbestos Inspection Report Chase Bank Branch – New Rochelle 270 North Avenue New Rochelle, New York 10801 OVP # 48100R006805

Apex Project No.: JPM001-0418070-23002979-051

Dear Ms. Pau:

JPMorgan Chase & Co. (JPMC) retained Apex Companies, LLC (Apex) to conduct a limited asbestos inspection of the planned renovation areas at the Chase Bank branch located at 270 North Avenue, New Rochelle, New York on March 29, 2023.

Executive Summary

Apex collected twenty-six (26) bulk samples of suspect asbestos containing materials (ACMs) from the interior and roof areas of the building to be affected by proposed renovations of the Chase Bank branch. The results of the asbestos inspection indicated that **asbestos was detected in the Pitch Pocket Tar on the Roof at greater than one percent and is considered an ACM. Asbestos was not detected in all other sampled materials and all other sampled materials are not considered ACM**. The results are summarized in the table below:

		Chase Ba	ank Brai 270 Nor	ary Data Table nch – New Rochelle th Avenue elle, New York		_	
MTL Group #	Material Description	Locations*	F/NF	Condition	%ACM	# Samples	Est. Quantity (SF/LF)*
1.	2' x 4' Acoustical Ceiling Tiles	Tenant Space Basement and present in the Lobby	NF	Good	ND	2	30 SF
2.	Spray-on Fire Proofing	Tenant Space Basement and present in the Lobby Plenum	F	Good	ND	3	40 SF
3.	Duct Vibration Cloth	Tenant Space Basement Plenum	NF	Good	ND	2	20 SF

RECEIVED PIKE 3/5/24

		Chase Ba	ank Brai 270 Nor	ary Data Table nch – New Rochelle th Avenue elle, New York			
MTL Group #	Material Description	Locations*	F/NF	Condition	%ACM	# Samples	Est. Quantity (SF/LF)*
4.	All-service Jacket	Tenant Space Basement Plenum	F	Damaged	ND	3	30 LF
5.	CMU Mortar	Tenant Space Basement	F	Good	ND	2	50 SF
6.	2' x 2' Acoustical Ceiling Tiles	ATM Room	NF	Good	ND	2	40 SF
7.	White Wallboard	ATM Room	F	Good	ND	2	100 SF
8.	White Joint Compound A/W White Wallboard	ATM Room	F	Good	ND	2	100 SF
9.	Pitch Pocket Tar	Roof	NF	Good	2.30% Chrysotile	2	10 SF
10.	Asphaltic Roof Membrane	Roof	NF	Good	ND	2	30 SF
11.	Tar and Tar Paper	Roof	NF	Good	ND	2	30 SF
12.	Fibrous Insulation	Roof	F	Good	ND	2	30 SF

Notes:

A/W - Associated With

F - Friable

NF - Not Friable

SF - Square Feet LF - Linear Feet

ND - Not Detected

ND - NOT Detect

MTL – Material

% ACM - Percentage of Asbestos Containing Material

* Locations and estimated quantities represent only those materials in the identified proposed renovation areas.

Sample Collection Procedures and Findings:

Apex representative Mr. Craig Diziki, a New York State licensed Asbestos Inspector, conducted an asbestos inspection of the targeted interior and roof areas of the bank branch scheduled for renovation. A copy of Mr. Diziki's asbestos inspector license is included in *Attachment 1*. The work was performed in accordance with the scope of work described in Apex's Proposal Number 11963600454 dated February 1, 2023, and the proposed Scope of Work provided by Chase. The Scope of Work for this project consisted



of a visual inspection and limited sampling of interior and roof suspect materials from accessible components for laboratory analysis that may be impacted by the proposed renovation activities identified in the design plans provided by Chase.

The bank is a single-story branch located in the 270 North Avenue in New Rochelle, New York complex. The exterior façade finishes include concrete block walls and columns, and glass windows and doors. The interior finishes within the proposed renovation areas include spray-on fireproofing, duct vibration cloth, all-service jacket, CMU mortar, wallboard, and acoustical ceiling tiles. Interior functional spaces in the proposed renovation areas include the tenant space basement, tenant space plenum, lobby plenum, and ATM room. The roofing finishes include the roofing system and pitch pocket tar. Apex focused its survey on the targeted interior and roof areas as described in the scoping documents provided by JPMC which include the replacement of the existing central air handling unit and corresponding condensing unit.

The bulk samples were analyzed using Polarized-Light Microscopy (PLM) and Transmission Electron Microscopy (TEM), following the New York State 198.1, New York State 198.6 NOB (Non-Friable) and New York State 198.4 NOB (Non-Friable) methods. The bulk samples were analyzed by the EMSL Analytical, Inc. (EMSL) asbestos laboratory located in Cinnaminson, New Jersey. The EMSL asbestos laboratory is accredited for asbestos PLM and TEM analyses by the National Institute of Standards and Technology National Voluntary Laboratory Accreditation Program (NVLAP). The NVLAP accreditation certificate for the EMSL asbestos laboratory is provided in *Attachment 1*. The suspect ACMs were sampled in general accordance with the EPA's Asbestos Hazard Emergency Response Act (AHERA) sampling protocol.

The laboratory report and chain of custody are provided in *Attachment* 2. The sample location diagram is provided as *Attachment* 3. Photographic documentation of the materials sampled is provided in *Attachment* 4.

The results of the asbestos inspection conducted of the Chase Bank branch determined that asbestos was detected in the Pitch Pocket Tar on the Roof at greater than one percent and is considered an ACM. Asbestos was not detected in all other sampled materials and all other sampled materials are not considered ACM. EPA defines an ACM as any material or product which contains greater than one (1) percent asbestos, as determined by using PLM or TEM.

Recommendations

Since ACMs are present, actions should be taken to prevent fiber release and to minimize exposure to employees and contractors to asbestos fibers. The following are Apex's recommendations for management of ACM.

- The identified ACMs that will be disturbed during the proposed renovation for the Chase Bank branch must be abated by a licensed contractor in accordance with a project design prepared by a licensed asbestos consultant and state/federal regulations prior to renovations. In addition, third party air monitoring must be performed during the abatement.
- Please note that state and federal regulations require a ten working day notification prior to any demolition or renovation activities that may impact the condition of ACM in a building that affords public access or occupancy.
- If the ACMs will remain in place, maintenance personnel, contractors, and other subcontractors should be made aware of the location of the ACM and the possibility of concealed suspect ACM that could be found during work activities or renovation activities. They should be advised to not disturb the identified suspect ACM.

This report is designed to aid the building owner, architect, construction manager, general contractors, and potential abatement contractors in locating ACM. Under no circumstances is the report to be utilized as a bidding document or as a project specification document since it does not have all the components required to serve as a Project Design document or an Abatement Work plan. <u>The quantities</u> of ACMs identified in this report are only estimates and should not be used for bidding or



<u>developing costs for abatement. It should be the responsibility of the abatement contractor to</u> <u>calculate actual quantities and develop removal costs accordingly.</u>

Any concealed building materials discovered during renovation activities not identified in this report, which are suspected to contain asbestos, should be sampled by a licensed asbestos inspector and analyzed by an NVLAP-accredited laboratory to confirm the absence or presence of asbestos prior to disturbing such materials. If the materials are found to contain asbestos, applicable local, state, and federal regulations will apply.

Apex appreciates the opportunity to be of service to JPMorgan Chase & Co. on this project. If you have questions or comments regarding the information in this report, please do not hesitate to contact the Apex office at (973) 479-6475.

Sincerely, **Apex Companies, LLC**

My NZ

Craig Diziki, ASP Assistant Project Manager

Attachments

nven

Veronica Parker Senior Project Manager

- Attachment 1: Apex Inspector and Laboratory Certifications/Accreditation
- Attachment 2: Laboratory Report and Chain of Custodies
- Attachment 3: Sample and Asbestos Location Diagram
- Attachment 4: Photographic Documentation



ATTACHMENT 1

APEX INSPECTOR AND LABORATORY CERTIFICATIONS/ACCREDITATION





WE ARE YOUR DOL

DIVISION OF SAFETY & HEALTH LICENSE AND CERTIFICATE UNIT, STATE OFFICE CAMPUS, BLDG. 12, ALBANY, NY 12226

ASBESTOS HANDLING LICENSE

Apex Companies, LLC 15850 Crabbs Branch Way, Suite 200, Rockville, MD, 20855

License Number: 29918 License Class: RESTRICTED Date of Issue: 12/05/2022 Expiration Date: 12/31/2023 Duly Authorized Representative: Stephen Choi

This license has been issued in accordance with applicable provisions of Article 30 of the Labor Law of New York State and of the New York State Codes, Rules and Regulations (12 NYCRR Part 56). It is subject to suspension or revocation for a (1) serious violation of state, federal or local laws with regard to the conduct of an asbestos project, or (2) demonstrated lack of responsibility in the conduct of any job involving asbestos or asbestos material.

This license is valid only for the contractor named above and this license or a photocopy must be prominently displayed at the asbestos project worksite. This license verifies that all persons employed by the licensee on an asbestos project in New York State have been issued an Asbestos Certificate, appropriate for the type of work they perform, by the New York State Department of Labor.

Amy Phillips, Director For the Commissioner of Labor

STATE OF NEW YORK - DEPARTMENT OF LABOR ASBESTOS CERTIFICATE





CRAIG R DIZIKI CLASS(EXPIRES) C ATEC(07/23) D INSP(07/23) H PM (07/23) I PD (07/23)

> CERT# 13-08178 DMV# 177909580

MUST BE CARRIED ON ASBESTOS PROJECTS

IN THE REDENDER OF REAL OF REAL BUSINESS.





Certificate of Accreditation to ISO/IEC 17025:2017

NVLAP LAB CODE: 101048-0

EMSL Analytical, Inc.

Cinnaminson, NJ

is accredited by the National Voluntary Laboratory Accreditation Program for specific services, listed on the Scope of Accreditation, for:

Asbestos Fiber Analysis

This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2017. This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality management system (refer to joint ISO-ILAC-IAF Communique dated January 2009).

2022-07-01 through 2023-06-30

Effective Dates



For the National Voluntary Laboratory Accreditation Program

SCOPE OF ACCREDITATION TO ISO/IEC 17025:2017

EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077 Ms. Samantha Rundstrom Phone: 856-303-2577 Email: srundstrom@emsl.com http://www.emsl.com

ASBESTOS FIBER ANALYSIS

NVLAP LAB CODE 101048-0

Bulk Asbestos Analysis

<u>Code</u>	<u>Description</u>
18/A01	EPA 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples
18/A03	EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials

Airborne Asbestos Analysis

<u>Code</u>

18/A02

Description

U.S. EPA's "Interim Transmission Electron Microscopy Analytical Methods-Mandatory and Nonmandatory-and Mandatory Section to Determine Completion of Response Actions" as found in 40 CFR, Part 763, Subpart E, Appendix A.

For the National Voluntary Laboratory Accreditation Program

ATTACHMENT 2

LABORATORY REPORT AND CHAIN OF CUSTODIES





EMSL	EMSL Analytical, Inc. 200 Route 130 North Cinnaminson, NJ 08077 Tel/Fax: (800) 220-3675 / (856) 786-5974 http://www.EMSL.com / cinnasblab@EMSL.com	EMSL Order: Customer ID: Customer PO: Project ID:	APXW25
Attention:	Don Wendt	Phone:	(732) 887-0783
	Apex Companies, LLC - NP	Fax:	
	58 Connecticut Avenue	Received Date:	03/30/2023 9:35 AM
	Suite H	Analysis Date:	04/04/2023 - 04/05/2023
	South Windsor, CT 06074-3452	Collected Date:	
Project:	APEX; JPM CHASE 270 NORTH AVENUE, NEW ROCHELLE, N	Y JPM001-0418070-2300	2979-051 (JPMC)
Frojeci.	ALEA, JI WIGHAGE 270 NORTH AVENUE, NEW ROCHELLE, N	1 31 1000 1-04 1807 0-2300	2373-031 (31 100)

	Analyzed			Non-Asbestos	
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID A-01		Description	TENANT SPACE BA	ASEMENT - 2' X 4' ACOUSTICAL CEILING TILE	E
042307742-0	001	Homogenei	ty Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	04/04/2023	Tan	5.00% Min. Wool	95.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	04/05/2023	Tan		100.00% Other	None Detected
Sample ID A-02		Description	TENANT SPACE BA	ASEMENT - 2' X 4' ACOUSTICAL CEILING TILE	E
042307742-0	002	Homogenei	ty Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	04/05/2023	Tan	7.00% Min. Wool	93.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	04/05/2023	Tan		100.00% Other	None Detected
Sample ID A-03		Description	TENANT SPACE BA	ASEMENT - SPRAY-ON FIREPROOFING	
042307742-0	003	Homogenei	ty Homogeneous		
PLM NYS 198.1 Friable	04/04/2023	Gray 6	0.00% Min. Wool	40.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID A-04		Description	TENANT SPACE BA	ASEMENT - SPRAY-ON FIREPROOFING	
042307742-0	004	Homogenei	ty Homogeneous		
PLM NYS 198.1 Friable	04/04/2023	Gray 6	0.00% Min. Wool	40.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID A-05		Description	TENANT SPACE PL	ENUM - SPRAY-ON FIREPROOFING	
042307742-0	005	Homogenei	ty Homogeneous		
PLM NYS 198.1 Friable	04/05/2023	Gray 4	5.00% Min. Wool	55.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed



200 Route 130 North Cinnaminson, NJ 08077 Tel/Fax: (800) 220-3675 / (856) 786-5974

http://www.EMSL.com / cinnasblab@EMSL.com

	Analyzed			I	Non-Asbestos	
Test	Date	Color		Fibrous	Non-Fibrous	Asbestos
Sample ID A-06		Descri	ption	TENANT SPACE PLE	NUM - DUCT VIBRATION CLOTH	
042307742-0	0006	Homog	geneity	Homogeneous		
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	04/04/2023	Black	<1.00	% Glass	100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	04/05/2023	Black			100.00% Other	None Detected
Sample ID A-07		Descri	ption	TENANT SPACE PLE	NUM - DUCT VIBRATION CLOTH	
042307742-0	0007	Homog	geneity	Homogeneous		
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	04/05/2023	Black			100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	04/05/2023	Black			100.00% Other	None Detected
Sample ID A-08		Descri	ption	TENANT SPACE PLE	NUM - ALL-SERVICE JACKET	
042307742-0	0008	Homog	geneity	Homogeneous		
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	04/04/2023	Silver	2.90	% Glass	97.10% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	04/05/2023	Silver			100.00% Other	None Detected
Sample ID A-09		Descri	ption	TENANT SPACE PLE	NUM - ALL-SERVICE JACKET	
042307742-0	0009	Homog	geneity	Homogeneous		
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	04/04/2023	Silver	11.00	% Glass	89.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	04/05/2023	Silver			100.00% Other	None Detected
Sample ID A-10		Descri	ption	TENANT SPACE PLE	NUM - ALL-SERVICE JACKET	
042307742-0	0010	Homog	geneity	Homogeneous		
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	04/05/2023	Silver	6.90	% Glass	93.10% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	04/05/2023	Silver			100.00% Other	None Detected
Sample ID A-11		Descri	ption	TENANT SPACE PLE	NUM - CMU MORTAR	
042307742-0	0011	Homo	geneity	Homogeneous		
PLM NYS 198.1 Friable	04/04/2023	Gray			100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed



200 Route 130 North Cinnaminson, NJ 08077 Tel/Fax: (800) 220-3675 / (856) 786-5974 http://www.EMSL.com / cinnasblab@EMSL.com EMSL Order: 042307742 Customer ID: APXW25 Customer PO: Project ID: JPMC

	Analyzed			Non-Asbestos	
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID A-12		Description	TENANT SPACE PLE	ENUM - CMU MORTAR	
042307742-0	012	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	04/05/2023	Gray		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID A-13		Description	ATM ROOM - 2' X 2'	ACOUSTICAL CEILING TILES	
042307742-0	013	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	04/04/2023	Tan 9.6	0% Min. Wool	90.40% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	04/05/2023	Tan		100.00% Other	None Detected
Sample ID A-14		Description	ATM ROOM - 2' X 2'	ACOUSTICAL CEILING TILES	
042307742-0	014	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	04/05/2023	Tan 7.4	0% Min. Wool	92.60% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	04/05/2023	Tan		100.00% Other	None Detected
Sample ID A-15		Description	ATM ROOM - WHITE	WALLBOARD	
042307742-0	015	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	04/04/2023		0% Cellulose 0% Glass	82.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID A-16		Description	ATM ROOM - WHITE	WALLBOARD	
042307742-0	016	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	04/05/2023		0% Cellulose 0% Glass	80.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID A-17		Description	ATM ROOM - WHITE	JOINT COMPOUND	
042307742-0	017	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	04/04/2023	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed



200 Route 130 North Cinnaminson, NJ 08077 Tel/Fax: (800) 220-3675 / (856) 786-5974

http://www.EMSL.com / cinnasblab@EMSL.com

	Analyzed			Non-Asbestos	
Test	Date	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID A-18		Description	ATM ROOM - WHITI	E JOINT COMPOUND	
042307742-	-0018	Homogene	ity Homogeneous		
PLM NYS 198.1 Friable	04/05/2023	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID A-19		Description	n ROOF - PITCH POC	KET TAR	
042307742-	-0019	Homogene	ity Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	04/05/2023	Black	None	97.70% Other	2.30% Chrysotile
TEM NYS 198.4 NOB					Not Analyzed
Sample ID A-20		Description	ROOF - PITCH POC	KET TAR	
042307742-	-0020	Homogene	ity		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	04/05/2023				Positive Stop (Not Analyzed)
TEM NYS 198.4 NOB					Not Analyzed
Sample ID A-21		Description	n ROOF - ASPHALITI	C ROOF MEMBRANE	
042307742-	-0021	Homogene	ity Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	04/04/2023	White/ Black	<1.00% Glass	100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	04/05/2023	White/ Black		100.00% Other	None Detected
Sample ID A-22		Description	n ROOF - ASPHALITI	C ROOF MEMBRANE	
042307742-	-0022	Homogene	ity Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	04/05/2023	White/ Black		100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	04/05/2023	White/ Black		100.00% Other	None Detected
Sample ID A-23		Description	ROOF - TAR AND TA	AR PAPER	
042307742-	0023	Homogene	ity Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	04/04/2023	Black	2.00% Glass	98.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	04/05/2023	Black		100.00% Other	None Detected



200 Route 130 North Cinnaminson, NJ 08077 Tel/Fax: (800) 220-3675 / (856) 786-5974 http://www.EMSL.com / cinnasblab@EMSL.com

	Analyzed			l	Non-Asbestos	
Test	Date	Color		Fibrous	Non-Fibrous	Asbestos
Sample ID A-24		Descri	ption	ROOF - TAR AND TA	R PAPER	
042307742-0	024	Homo	geneity	Homogeneous		
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	04/05/2023	Black	<1.00	% Glass	100.00% Other	Inconclusive: None Detected
TEM NYS 198.4 NOB	04/05/2023	Black			100.00% Other	None Detected
Sample ID A-25		Descri	ption	ROOF - FIBROUS IN	SULATION	
042307742-0	025	Homo	geneity	Homogeneous		
PLM NYS 198.1 Friable	04/04/2023	Brown	80.00	% Cellulose	20.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID A-26		Descri	ption	ROOF - FIBROUS IN	SULATION	
042307742-0	026	Homo	geneity	Homogeneous		
PLM NYS 198.1 Friable	04/05/2023	Brown	90.00	% Cellulose	10.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed

EMSL

EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077 Tel/Fax: (800) 220-3675 / (856) 786-5974 http://www.EMSL.com / cinnasblab@EMSL.com EMSL Order: 042307742 Customer ID: APXW25 Customer PO: Project ID: JPMC

Test Report: Asbestos Analysis of Bulk Material

Analyst(s):

Amy Schulze PLM NYS 198.1 Friable (5)

Amy Schulze PLM NYS 198.6 NOB (7)

Ted Young TEM NYS 198.4 NOB (13)

Samples reviewed and approved by:

Julianna Hosbach PLM NYS 198.1 Friable (6)

Julianna Hosbach PLM NYS 198.6 NOB (7)

montha Kinghano

Samantha Rundstrom, Laboratory Manager or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. Estimation of uncertainty available upon request. This report is a summary of multiple methods of analysis, fully compliant reports are available upon request. All samples examined for the presence of vermiculite when analyzed via NYS 198.1. A combination of PLM and TEM analysis may be necessary to ensure consistently reliable detection of asbestos . Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. This report must not be used to claim product endorsement by NVLAP of any agency or the U.S. Government . Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing. NOB= Non friable organically bound; N/A= Not applicable VCM= Vermiculite containing material.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NYS ELAP 10872, PA ID# 68-00367, NVLAP Lab Code 101048-0

Initial report from: 04/05/2023 12:15:03

Name:	Apex Con	Apex Companies, LLC	Facility:	Chase Branc	Chase Branch – New Rochelle	Project #:	JPM001-04	Page _	Page	Page02979-051
Z Address:	485 Routi	485 Route 1 South –Building B	H Address:	270 North Avenue		D Apex Manager:	CEIVED	Don Wendt	endt	
City, State, Zip: Iselin, NJ 08830	p: Iselin, N.	J 08830	City, State, Zip:	New Rochelle, NY		Emai		INSON craigldiziki@apexcos.com	pexcos.col	UNIT
						7073 MAR 30	30 PH I	PH 12: 4 Bbservations	ions	
Sample #	HA#	Materia	Material Description		Location	Classification	Friable?	Condition	Approx. Quantit # SF/	Quantit SF/
A-01		2'X4' Aloustrian	(ei ling	FUL TENU	ant Space Basement	Mise. TSI Surfacing	Y IÂ	G D SD	202	5.4
A-02	2		C			Misc. TSI Surfacing	YIN	DISD	\rightarrow	>
A-03	~	Splay- On F	Fire prosfing			Misc. TSI Surfacing	Q I N	Ĝ D S D	14,0	51
A-04			-			Misc. TSI Surfacing	N I Y	G D SD	2	
4-05		3			Plenum 1	Misc. TSI Surdacing	VIN	G D SD	2	
A-06	R.	Duct Vibration	von Cloth			Misc. TSI Surfacing	Y I (N	G D S D	240	SF
A-07	2				2	Misic. TSI Surfacing	Y IN	G D S D		Ð
A-02	Ч	Alt Service	Jacket			Misc. (13) Surfacing	z Ø	G 🕲 S D	22	5
A-09		-				Misc. TSI Surfacing	N I X	G D S D	\rightarrow	
4-10	\geq	\searrow				Misc. ISI Surfacing	N I N	GINGISD	2	\geq
A-11	5	(DAI) MOR	oftar			Misc. TSI Surfacing	NI	GDDD	50	54
A-12	>					Misc. TSI Surfacing	N	& D SD	S	2
A-13	9.	2'x2' Acoustical	Ceching	Tr'185 Z	ATM ROOM	Misc. TSI Surfacing	γI	G D S D	N()	SF
H-1-4	2		· r p		2	Mise. TSI Surfacing	¥1%	¢ D S D	0	2
ampling Date:	3/24/23 212	Collected by (print):	Craig Diziki		Inspector's Signature: Und U.O.					
Selinquished by:	and .	22	Date/Time:	Date/Time: 3/29/23	2-II Received by: 0 1 FX		Date/Time:	le: 3/30/	S	1.30
nalysis: PLM EPA 600	A 600	OB	PLM - NOB		Comments: - Positive Stop		(
⁰ urnaround Time: 24 hrs 48 hrs x	24 hrs	77 hrs	96 hrs 1 week	2 week			0000			

	APEX	ASBESTOS INSPECTION CHAIN OF CUSTODY FORM	z S	Σ	#042307742	142
 	Name:	Apex Companies, LLC	-	Facility:	Chase Branch – New Rochelle	RE
LNI	Address:	485 Route 1 South –Building B	3TTR	Address:	270 North Avenue	CINNA
CC	City, State, Zip:	City, State, Zip: Iselin, NJ 08830	5	City, State, Zip:	City, State, Zip: New Rochelle, NY	CAM CLUL
1						R HAR CANA

STOS INSPECTION	7		#0423	#042307742	Laboratory Order ID:	rder ID:			
N OF CUSTODY FORM	ORM						EN	EMSL Account #: APA	#: APX
ipanies, LLC	Facility:	Chase B	Branch – New Rochelle	RE	CEI Project #:	JPM001-0	JPM001-0418070-23002979-051	979-051	
e 1 South –Building B	H Address:	270 Noi	270 North Avenue	CINNAM	D Apex Manager:		Don Wendt	endt	
08830	City, State, Zip: New		Rochelle, NY	2023 MAR 30	Email Results To:		craig.diziki@apexcos.com	pexcos.col	۶
							Observations	tions	
Materia	Material Description		location		Classification	Friable?	Condition	Approx. Quantit # SF/	Quantit SF/
White wall board	board		ATM ROOM		Misco TSI Surfacing	N	G D S D	601	St.
-2	Å				Misc. TSI Surfacing	N X	G D SD		
White The	toint Conpound	2			Misc. TSI Surfacing	N	GDSD		
	N			dia :	Mise: TSI Surfacing	NN	GDSD	\rightarrow	\geq
Pitch DOCKET	et tar		Roof		Misc. TSI Surfacing	× 1 ©	G D S D	i()	55
2				4 2 B	Mse. TSI Surfacing	VIV	CA DISD	\rightarrow	5
AGDINULTIC R	Roof Membrane	2		E	Misc. TSI Surfacing	Y I N	GDDD		
-					Misc. TSI Surfacing	V I V	GDDD		
tar and t	ar and tur Paper				Misc. TSI Surfacing	X I V	GDSD		
7	-				Misc. TSI Surfacing	X M	6 D S D		

V 1 \rightarrow

S

1

HA#

Sample #

9

1-11

2 OE Page

G D SD

N

Misc. | TSI | Surfacing

Insulation

Fibrous

3

A-25

-

423

274

2

>

02-3

5

101-

4-15

2

N

 \rightarrow

3

426

DSD

20

NIN

Misc. | TSI | Surfacing

G D SD

N X

Misc. | TSI | Surfacing

G D SD

N X

Misc. | TSI | Surfacing

Positive Stop Comments:

Date/Time:

52

m

Inspector's Signature:

Date/Time: 3/29/23 2:11 Received by:

042307742 **** Collected by (print): Craig Diziki

7

ATTACHMENT 3

SAMPLE AND ASBESTOS LOCATION DIAGRAM











LEGEND

NEGATIVE ASBESTOS SAMPLE

POSITIVE ASBESTOS SAMPLE

ACM POSITIVE PITCH POCKET TAR

CHK BY	CD
DWN BY	EM
DATE	03-31-23
SCALE	NTS
CAD NO.	0418070-23002979.51
PRJ NO.	JPM001-0418070-23002979

SAMPLE LOCATION DIAGRAM ROOF

> NEW ROCHELLE 270 NORTH AVENUE

NEW ROCHELLE, NEW YORK



ATTACHMENT 4

PHOTOGRAPHIC DOCUMENTATION





270 North Avenue New Rochelle, NY 10801

Photograph: Description:	1 Exterior view of the Chase Bank branch located at 270 North Avenue, New Rochelle, NY.	
Photograph: Description:	2 HA-1 2'x4' acoustical ceiling tile sampled in the tenant space basement and present in the lobby.	
Photograph: Description:	3 HA-2 spray-on fireproofing sampled in the tenant space basement plenum and present in the lobby plenum.	



Site Photographs - 03/29/2023 Apex Companies, LLC

270 North Avenue New Rochelle, NY 10801

Photograph: Description:	4 HA-3 duct vibration cloth sampled in the tenant space basement plenum.	
Photograph: Description:	5 HA-4 all service jacket sampled in the tenant space basement plenum.	
Photograph: Description:	6 HA-5 CMU mortar sampled in the tenant space basement.	



Site Photographs - 03/29/2023 Apex Companies, LLC

270 North Avenue New Rochelle, NY 10801

Photograph: Description:	7 HA-7 white wallboard and HA-8 white joint compound sampled in the ATM room.	
Photograph: Description:	8 HA-9 pitch- pocket tar, HA-10 asphaltic roof membrane, HA-11 tar and tar paper, and HA-12 fibrous insulation sampled from the roof.	

