

SCHEDULE "A"
SCOPE OF SERVICES

Yonkers Public Schools
School Facilities Management
School 25 Boiler repairs
Subject Boiler: Boiler # 2 Weil McLain Series 94
Scope of Work:

- 1 - Remove and replace Rear section and Intermediate section
- 2 – Furnish and Install 2 new sections with all associated ropes and gaskets, etc.
- 3 – Hydro test boiler for leaks
- 4 – Reinstall outer jacket
- 5 – Reconnect breeching connector
- 6 – Reconnect piping
- 7 – Remove and discard old sections from site
- 8 – Test run boiler for leaks