Bankof America >>



GENERAL NOTES

- 1. THE GENERAL SCOPE OF WORK DESCRIBED HERE INVOLVES THE COMPLETE REPLACEMENT OF THE MASONRY PARAPETS AT THE MAIN ROOF ALONG THE SOUTH & EAST ELEVATIONS, AS SHOWN HEREIN.
- 2. ALL CONSTRUCTION TO BE IN ACCORDANCE WITH THE RULES AND REGULATIONS OF THE CITY OF YONKERS AND NEW YORK STATE BUILDING CODE.
- 3. THE CONTRACTOR SHALL FAMILIARIZE HIMSELF WITH REQUIREMENTS OF SAFETY OF PUBLIC PROPERTY DURING CONSTRUCTION OPERATIONS AND SHALL BE HELD RESPONSIBLE FOR SAFE MAINTENANCE OF THE WORKSITE UNTIL COMPLETION AND FINAL ACCEPTANCE OF THE WORK.
- 4. THE FOLLOWING SHALL BE MADE UNDER SEPARATE
- SIDEWALK SHEDS
- 5. ALL MASONRY UNITS SHALL CONFORM TO THE BUILDING CODE. MASONRY WALLS AND CONSTRUCTION SHALL CONFORM TO NEW YORK STATE BUILDING CODE.
- 6. THE CONTRACTOR SHALL BE RESPONSIBLE FOR FILING WITH AND OBTAINING PERMITS FROM, AND OBTAINING SIGN-OFFS FROM THE DEPARTMENT OF BUILDINGS AS
- 7. ALL DETAILS ARE TYPICAL AND ARE INDICATED ONCE.
- 8. ALL DIMENSIONS TO BE VERIFIED IN FIELD.

- 9. AT THE ROOF MAKE NECESSARY REPAIRS INCLUDING BUT NOT LIMITED TO THE FOLLOWING: 9.1 FURNISH AND INSTALL A FULL METAL JACKET TO
- THE EXISTING SECTIONS OF HVAC DUCTWORK TO 9.2 MAKE NECESSARY REPAIRS TO THE SKYLIGHT TO
- ACHIEVE WATER TIGHTNESS TO INCLUDE 9.2.1 REMOVE ALL GLASS AND GLAZING (PUTTY, ETC.), REPLACE ALL GLASS TO MATCH EXISTING. 9.2.2 SALVAGE AND REINSTALL COPPER CAPS. 9.2.3 INSTALL GLASS WITH NEW PUTTY.
- 9.2.4 REPLACE EXISTING BASE FLASHING WITH NEW TO MATCH EXISTING AND COORDINATE WITH ROOFING SYSTEM.
- 9.3 CAREFULLY REMOVE EXISTING CONDUIT MOUNTED TO EXISTING PARAPET AND RE-INSTALL MOUNTED TO NEW RE-BUILT PARAPET.
- $\stackrel{()}{>}$ 10. LANDLORD TO REVIEW EXISTING CONDITIONS AT EXISTING CORNICE & PARAPETS, AND EXISTING MASONRY SUBSTRATES BEHIND EXISTING GRANITE PANELS AND STUCCO APPLICATION (REFERENCE REPAIR TASKS 1, 5, 8, 8a & 10). LANDLORD TO REPORT FINDINGS TO TENANT. ANY AGREED UPON ADDITIONAL REMEDIAL WORK TO BE ADDRESSED BY THE TENANT.
- √
 ≥
 √
 √
 ↑
 11. EXISTING FIRE ESCAPES TO BE REMOVED AND REPLACED. GC TO PROVIDE SHOP DRAWINGS OF NEW FIRE ESCAPES TO ARCHITECT AND STRUCTURAL ENGINEER FOR REVIEW.

TENANT SAFETY NOTES

- CONSTRUCTION WORK SHALL NOT CREATE DUST, DIRT, OR OTHER SUCH INCONVENIENCES TO SPACES WITHIN THE
- CONSTRUCTION OPERATIONS SHALL NOT BLOCK
- CONSTRUCTION OPERATIONS SHALL NOT INVOLVE INTERRUPTION OF HEATING, WATER, OR ELECTRICAL SERVICES TO OTHER TENANTS OF THE BUILDING, UNLESS SPECIFICALLY AUTHORIZED BY THE BUILDING MANAGEMENT.
- 4. CONSTRUCTION OPERATION SHALL BE CONFINED TO NORMAL WORKING HOURS: 9 AM TO 5 PM, MONDAY THROUGH FRIDAY, EXCEPT LEGAL HOLIDAYS.
- 5. IT SHALL BE THE RESPONSIBILITY OF THE CONTRACTOR TO PROVIDE ALL TEMPORARY MEASURES NECESSARY TO PROTECT THE PREMISES FROM WATER DAMAGE DURING THE COURSE OF THE WORK AND REPAIR ALL DAMAGE CAUSED BY HIM WITH NEW MATERIALS TO MATCH EXISTING THE SATISFACTION OF THE OWNER, ARCHITECT AND/OR ENGINEER.

REMOVAL NOTES

1. THE CONTRACTOR SHALL BE FAMILIAR WITH AND PERFORM ALL REMOVAL WORK IN ACCORDANCE WITH NEW YORK STATE BUILDING CODE.

STRUCTURAL STEEL NOTES

- 1. ALL DETAILING, FABRICATION AND ERECTION SHALL CONFORM TO AISC "SPECIFICATION FOR STRUCTURAL STEEL BUILDINGS" AND AISC "CODE OF STANDARD PRACTICE FOR STEEL BUILDINGS AND BRIDGES", LATEST EDITIONS.
- 2. ALL BOLTING SHALL CONFORM TO THE RESEARCH COUNCIL ON STRUCTURAL CONNECTIONS "SPECIFICATION FOR STRUCTURAL JOINTS USING
- ASTM A325 OR A490 BOLTS", LATEST EDITION. 3. ALL WELDING SHALL CONFORM TO THE AWS CODE D1.1 "STRUCTURAL WELDING CODE - STEEL", LATEST EDITION.
- 4. THE FABRICATOR/ERECTOR SHALL SUBMIT TO THE AND CHECKED DRAWINGS SHOWING SHOP FABRICATION DETAILS, FIELD ASSEMBLY DETAILS AND ERECTION DRAWINGS AND JOB STANDARDS DESCRIBING TYPICAL CONNECTION DETAILS AND CAPACITIES SHALL BE SUBMITTED AND APPROVED PRIOR TO THE START OF PIECE DETAILING.
- 5. ALL FIRE ESCAPE STRUCTURES AND MISCELLANEOUS STEEL SHALL BE DESIGNED AND DETAILED BY A NEW YORK STATE REGISTERED PROFESSIONAL ENGINEER HIRED BY THE CONTRACTOR. THE FABRICATOR/ERECTOR SHALL SUBMIT TO THE ENGINEER OF RECORD, FOR REVIEW, ENGINEERED AND CHECKED DRAWINGS SHOWING SHOP FABRICATION DETAILS, FIELD ASSEMBLY DETAILS, ERECTION DIAGRAMS, AND CALCULATIONS. ALL STAIR STEEL SHOP DRAWINGS AND DESIGN SIGNATURE OF THE CONTRACTOR'S ENGINEER.

- 6. ALL STRUCTURAL STEEL SHALL COMPLY WITH THE
- WIDE FLANGES SQUARE OR ROUND TUBE

DTI WASHERS

- ANGLE AND CHANNEL ASTM A36 STAINLESS STEEL AISI 304 OR AISI 316 ANCHOR BOLTS/RODS ASTM F1554 HARDENED WASHERS ASTM F436
- ENGINEER OF RECORD, FOR REVIEW, ENGINEERED 7. ALL WELDING SHALL BE PERFORMED BY AWS
- ERECTION DIAGRAMS FOR ALL STRUCTURAL STEEL. 8. MINIMUM FILLET WELD SIZES SHALL COMPLY WITH THE NOTED OTHERWISE.

ASTM F959

- 9. ALL FIELD WELDING ELECTRODES SHALL BE E70XX LOW HYDROGEN. SHOP WELDING ELECTRODES SHALL BE E70XX LOW HYDROGEN. ALL FILLER METAL SHALL HAVE A MINIMUM CHARPY V-NOTCH (CVN) TOUGHNESS OF 20 FT. LBS. AT MINUS 20 DEGREES F.
- 10. SHOP AND FIELD TESTING OF WELDS AND BOLTS SHALL BE AS FOLLOWS: ALL WELDS SHALL BE VISUALLY INSPECTED.
- CONNECTION PLATES (15 % AT RANDOM) SHALL BE CHECKED BY MAGNETIC PARTICLE FOR FINAL

- FOLLOWING UNLESS OTHERWISE NOTED:
- ASTM A992 GR 50 ASTM A500-GR B, FY=46 KSI. PIPES ASTM A53, FY=35 KSI HIGH STRENGTH BOLTS ASTM A325 OR A490 (MIN. $\frac{3}{4}$ " DIAM. UNO)
- QUALIFIED WELDERS.
- AISC. BUT SHALL NOT BE LESS THAN 1/4 INCH. UNLESS
 - OTHERWISE.
- 15% AT RANDOM SHALL BE MEASURED.
 - SHALL BE HOT DIP GALVANIZED PER ASTM A123, 2 OZ

Kimball Avenue

PLOT PLAN

LIST OF DRAWINGS:

SHEET #	DRAWING TITLE	
T-001.00	TITLE SHEET	
A-101.00	ELEVATIONS	
A-102.00	ROOF PLAN	
A-103.00	PARAPET WALL REMOVAL SECTIONS	
A-104.00	NEW PARAPET SECTIONS	
A-201.00	DETAILS	
A-202.00	DETAILS	
A-203.00	ROOF DETAILS	
A-301.00	CONDITION PHOTOGRAPHS	
S-001.00	STRUCTURAL NOTES	
S-102.00	2ND FLOOR FRAMING PLAN	
S-103.00	ROOF FRAMING PLAN	
S-200.00	SECTIONS & DETAILS	




PHOTO INDICATOR

PASS ONLY.

- C. ULTRASONICALLY TEST 100% OF ALL FULL PENETRATION WELDS.
- CHECK ALL PRETENSIONED BOLTS BY EITHER THE T/C METHOD OR BY CALIBRATED TORQUE WRENCH. IN EACH SHEAR CONNECTION, CHECK 100% OF BOLTS WHEN USING T/C METHOD AND 25% OF BOLTS WITH OTHER METHOD FOR EACH SHEAR CONNECTION, BUT NOT LESS THAN TWO (2) BOLTS PER CONNECTION.
- E. CHECK ALL SLIP CRITICAL BOLTS WITH THE "DIRECT TENSION INDICATOR" METHOD. ALL BOLTS SHALL BE VISUALLY INSPECTED. MEASURE WITH FEELER GAGES, AT LEAST 15 PERCENT OF BOLTS IN EACH CONNECTION, BUT NOT LESS THAN TWO BOLTS PER
- THE OWNER'S SPECIAL INSPECTOR OR TESTING AGENCY SHALL PERFORM ALL SHOP AND FIELD INSPECTION AND TESTING AS OUTLINED ABOVE.

CONNECTION.

- FABRICATE SIMPLY SUPPORTED BEAMS WITH NATURAL CAMBER UP, FABRICATE CANTILEVER BEAMS WITH NATURAL CAMBER DOWN, UNLESS NOTED
- 12. GAS OR ARC CUTTING OF NEW OR EXISTING SECTIONS IS NOT ALLOWED. GAS OR ARC CUTTING TO ENLARGE EXISTING OR NEW BOLT HOLES IS NOT ALLOWED. GAS OR ARC CUTTING TO CREATE NEW HOLES IN EXISTING OR NEW STEEL IS NOT ALLOWED.
- ALL STEEL EXPOSED TO WEATHER OR AS INDICATED

PER SQ. FOOT MINIMUM DEPOSITION, INCLUDING DUNNAGES, STEEL LINTELS, SHELF ANGLES, LINTEL HANGERS, AND ALL OTHER STEEL FRAMING OUTSIDE THE BUILDING ENVELOPE.

CONSTRUCTION TO REMAIN

14. PROVIDE 3-COAT TNEMEC PAINT SYSTEM (OR APPROVED EQUAL) FOR NEW FIRE ESCAPES OR AS NOTED AS FOLLOWS:

90-97 TNEME-ZINC AT 2.5 - 3.5 MILS DFT

INTERMEDIATE COAT:

27 FC TYPOXY, OR

ARCHITECT/OWNER.

V69F EPOXOLINE II, 4-6 MILS DFT FINISH COAT: 73 ENDURA-SHIELD AT 2-3 MILS DFT COLOR OF FINISH COAT TO BE SELECTED BY

11.08.2021 ISSUED FOR LANDLORD COMMENT 10.14.2021 ISSUED FOR LANDLORD COMMENT 07.15.2021 ISSUED FOR PERMIT & PRICING VI 03.24.2021 ISSUED FOR PERMIT & PRICING V 02.03.2021 ISSUED FOR PERMIT & PRICING II 10.12.2020 ISSUED FOR LANDLORD REVIEW 08.18.2020 ISSUED FOR LANDLORD REVIEW 08.07.2020 ISSUED FOR REVIEW 05.12.2020 REVISED 04.27.2020 REVISED

04.13.2020 ISSUED FOR REVIEW

o Date | Revisions

06.25.2019 ISSUED FOR LANDLORD REVIEW

Bankof America 🔷

Global Corporate Services

Email: margaret.dilorenzo@cbre.com

Gilsanz Murray Steficek LLP

Email: Mark.Beltramello@GMSLLP.com Email: Jonathan.Hernandez@GMSLLP.com Attn: Mark Beltramello / Jonathan Hernandez

Alexander Avenue

Parking Lot

1133 Avenue of the Americas New York, NY 10036 T: 914.299.0078

Attn: Margaret DiLorenzo

Structure / Building Envelope 129 West 27th Street, 5th Fl. New York, NY 10001 T: 212.254.0030



Bank of America

Facade Repairs and Roof Replacement 928 McLean Avenue, Yonkers, NY 10704


Drawing Title:

TITLE SHEET

18581

T-001.00 06.25.2019 Drawn By: Scale: PAGE 01 OF 0

FACADE REPAIR AND ROOF REPLACEMENT WORK AT 928 McLEAN AVE, YONKERS, NY



EXIST ATTIC .

VENT TO REMAIN

EXIST ATTIC

VENT TO REMAIN

SOUTH ELEVATION REMOVE AND REBUILD (2) TWO WYTHE PARAPET WALL. 3'HX60LF=180 SF (APPROX.). REPLACE METAL COPING WITH NEW TO MATCH EXISTING SEE

REPAIR TASKS

REMOVE AND REBUILD (2) TWO WYTHE PARAPET. 3'HX 16LF=48 SF (APPROX.) AND REPLACE METAL

RAKE OUT AND REPOINT (MIN. 3/4" DEPTH) ENTIRE REMAINING FACADE 1,100 SF (APPROX.) PER DETAIL

RAKE OUT AND REPOINT (MIN. 3/4" DEPTH) ENTIRE REMAINING FACADE 2,100 SF. (APPROX.). PER DETAIL

RAKE OUT AND REPOINT (MIN. 3/4" DEPTH) ENTIRE FACADE 2,300 SF. (APPROX.). PER DETAIL 6/A201.00 RAKE OUT AND REPOINT (MIN 3/4" DEPTH) ON THE

REPLACED. GC TO PROVIDE SHOP DRAWINGS TO THE STRUCTURAL ENGINEER AND ARCHITECT FOR REVIEW. PATCH AND REPAIR ADJACENT MASONRY

4> EAST ELEVATION

REMOVE, REPLACE AND WATERPROOF EXTERIOR WINDOW LINTELS ONLY (100LF) WITH NEW GALVANIZED STEEL LINTEL. DIMENSIONS TO MATCH EXISTING. SEE DETAIL 1/A201.00. NORTH ELEVATION

REMOVE, REPLACE AND WATERPROOF EXTERIOR WINDOW LINTELS ONLY (40 LF). INSTALL NEW GALVANIZED STEEL LINTEL INCLUDING ASSOCIATED MASONRY WORK. DIMENSIONS TO MATCH EXISTING. SEE DETAIL 1/A201.00.

SOUTH ELEVATION

REMOVE. REPLACE AND WATERPROOF EXTERIOR WINDOW LINTELS ONLY (40 LF). INSTALL NEW GALVANIZED STEEL LINTEL INCLUDING ASSOCIATED MASONRY WORK, DIMENSIONS TO MATCH EXISTING. SEE DETAIL 1/A201.00.

REMOVE, REPLACE AND WATERPROOF EXTERIOR WINDOW LINTELS ONLY (80 LF). INSTALL NEW GALVANIZED STEEL LINTEL INCLUDING ASSOCIATE MASONRY WORK. DIMENSIONS TO MATCH EXISTING.

6 NORTH ELEVATION PROVIDE (2) TWO COATS OF A BREATHABLE ELASTOMERIC COATING (DOW ALLGUARD OR EQUAL) TO THE ENTIRE FACADE. COLOR TO BE

7 THROUGH-WALL FLASHING PROVIDE 2 PIECE 22 GAUGE STAINLESS THROUGH-WALL FLASHING AT SOUTH ELEVATION

ALL GRANITE PANELS AT 1ST FLOOR OF THE SOUTH, WEST AND EAST ELEVATIONS TO BE REMOVED AND REPLACED WITH NEW PANELS SUBMIT SAMPLES AND SHOP DRAWINGS FOR REVIEW. ALL ANCHORS TO BE STAINLESS STEEL TYPE 304. PROVIDE CLOSED-CELL BACKER ROD

SOUTH ELEVATION EXISTING GRANITE CLADDING AT ENTRANCE RECESSED VESTIBULE AREA TO BE REMOVED. PROVIDE STUCCO FINISH PER DETAILS 7, 7a AND 7b/A-201.00. COLOR TO BE SELECTED BY

10 NORTH ELEVATION PATCH & REPAIR EXISTING BRICK PARAPET TO MATCH ADJACENT WHERE EXISTING STEEL DUNNAGE SUPPORTS ARE REMOVED. REFERENCE DETAIL 4/A201.00. SEE GENERAL NOTE 10.

(12) WEST ELEVATION REMOVE/SEAL EMBEDDED ANCHORS, SEE DETAIL

(13) WINDOW REPLACEMENT NORTH, EAST, WEST AND SOUTH ELEVATIONS TO BE REMOVED DOWN TO MASONRY OPENING AND REPLACED WITH NEW ANDERSEN 400 SERIES WINDOWS. CONTRACTOR TO VERIFY OPENING DIMENSIONS IN FIELD. SEE DETAILS 1, 1A AND 1B/A201.00. PROVIDE WINDOW SHOP DRAWINGS

(14) <u>ROOF</u> SYSTEM AS SHOWN ON DETAIL A ON A-203.00. ROOF SHEATHING. ASSUME 50% OF PLYWOOD SHEATHING REPLACEMENT.

(15) RELOCATED ROOF EQUIPMENT. PROVIDE PREFABRICATED CURB WITH INSULATED CORE, ON A-203.00.

(16) EXISTING ROOF EQUIPMENT TO BE TEMPORARILY DISCONNECTED, RAISED AND RECONNECTED. PREFABRICATED CURB WITH INSULATED CORE, ON A-203.00.

NEW ROOF EQUIPMENT. PROVIDE PREFABRICATED CURB WITH INSULATED CORE, THYCURB OR APROVED EQUAL. COORDINATE WORK WITH MEP DRAWINGS. REFER TO DETAILS 7 AND 9 ON A-203.00.

REPLACED. REFER TO DETAIL 6/A-203.00. (21) LINTEL ABOVE STOREFRONT TO BE PROBED DURING CONSTRUCTION FOR ENGINEER'S REVIEW. COORDINATE PROBE LOCATION WITH TENANT.

Bankof America 🔷

Global Corporate Services

Email: margaret.dilorenzo@cbre.com

Gilsanz Murray Steficek LLP

Email: Mark.Beltramello@GMSLLP.com

Email: Jonathan.Hernandez@GMSLLP.com

Attn: Mark Beltramello / Jonathan Hernandez

Alexander Avenue

Parking Lot

Kimball Avenue

Project Management

1133 Avenue of the Americas New York, NY 10036 T: 914.299.0078

Attn: Margaret DiLorenzo

Structure / Building Envelope

129 West 27th Street, 5th Fl.

New York, NY 10001

KEY PLAN Z

T: 212.254.0030

WEST ELEVATION

SEE DETAIL 1/A201.00.

5 NORTH ELEVATION EXISTING STUCCO FINISH TO BE REMOVED DOWN TO SUBSTRATE IN ITS ENTIRETY. ALL OPEN/ERODED MORTAR JOINTS TO BE RAKED OUT AND REPOINTED. PROVIDE NEW STUCCO STO SYSTEM. ASSUMED A TOTAL OF 1000 SF OF STUCCO REPLACEMENT AND 500 SF OF MORTAR JOINT REPOINTING PER DETAILS 5, 5a and 5b/A202.00. SEE GENERAL NOTE 10.

SELECTED BY ARCHITECT.

PER DETAIL 1/A103.00.

(8) GRANITE PANELS AND SEALANT DOWSIL 756 SMS TO JOINTS. COLOR TO BE SELECTED BY ARCHITECT. SEE DETAILS 1, 2 AND 3/A-202.00. SEE GENERAL NOTE 10.

ARCHITECT. SEE GENERAL NOTE 10.

PATCH DAMAGED CONCRETE TOP AT CHIMNEY.

11> WEST ELEVATION CRACKED BRICK CONTINGENCY 250 SF, SEE DETAIL 4/A201.00. NEW BRICK MASONRY TO MATCH EXISTING IN ALL RESPECTS.

ALL EXISTING WINDOWS AT THE 2ND FLOOR OF THE FOR REVIEW.

(3a) WEST ELEVATION PROVIDE SEALANT AT LOUVER PERIMETER. ASSUME 50 LF.

REMOVE ALL EPDM ROOFING AND FLASHING SYSTEMS DOWN TO EXISTING WOOD DECK, INCLUDING BUT NOT LIMITED TO PENETRATION POCKETS, INSULATION, OTHER MEMBRANES ETC. PROVIDE NEW ROOFING REMOVE/REPLACE DAMAGED EXISTING PLYWOOD SHEATHING AS REQUIRED WITH NEW \(\frac{3}{4}\)" THICK WOOD

THYCURB OR APROVED EQUAL. REFER TO DETAIL 9

COORDINATE WORK WITH MEP DRAWINGS. PROVIDE THYCURB OR APROVED EQUAL. REFER TO DETAIL 9

18 EXISTING EQUIPMENT CURB TO BE REMOVED. PROVIDE NEW INSULATED CORE CURB. THYCURB OR APPROVED EQUAL. FLASH PER DETAIL 9 ON A-203.00.

(19) EXISTING ELECTRICAL CONDUITS TO BE TEMPORARILY DISCONNECTED AND RAISED TO ALLOW FOR ROOFING INSTALLATION. REMOVE/ OR REINSTALL CONDUITS AS REQUIRED. COORDINATE WITH MEP DRAWINGS. 20 EXISTING SCUPPERS TO BE REMOVED AND

04.13.2020 ISSUED FOR REVIEW 06.25.2019 ISSUED FOR LANDLORD REVIEW lo Date Revisions ENGINEERS & ARCHITECTS
129 West 27 Street
New York, New York 10001
212-254-0030, fax.212-477-5978
www.gmsllp.com

11.08.2021 ISSUED FOR LANDLORD COMMENT 10.14.2021 ISSUED FOR LANDLORD COMMENT

07.15.2021 ISSUED FOR PERMIT & PRICING VI

03.24.2021 ISSUED FOR PERMIT & PRICING V

02.03.2021 ISSUED FOR PERMIT & PRICING II

10.12.2020 ISSUED FOR LANDLORD REVIEW

08.18.2020 ISSUED FOR LANDLORD REVIEW

08.07.2020 ISSUED FOR REVIEW

05.12.2020 REVISED 04.27.2020 REVISED

GILSANZ.MURRAY.STEFICEK.LLP Project:


Bank of America

Facade Repairs and Roof Replacement 928 McLean Avenue, Yonkers, NY 10704

Drawing Title: **ELEVATIONS**

18581 06.25.2019 Drawn By: Scale: As Noted

A-101.00 PAGE 02 OF 09



REPAIR TASKS

GENERAL NOTE 10.

DETAIL 6/A201.00

AS REQUIRED.

SOUTH ELEVATION
REMOVE AND REBUILD (2) TWO WYTHE PARAPET
WALL. 3'HX60LF=180 SF (APPROX.). REPLACE METAL
COPING WITH NEW TO MATCH EXISTING . SEE
DETAILS 2/A103.00 AND 3 AND 4/A104.00. SEE

EAST ELEVATION
REMOVE AND REBUILD (2) TWO WYTHE PARAPET.
3'HX 16LF=48 SF (APPROX.) AND REPLACE METAL
COPING WITH NEW TO MATCH EXISTING . SEE
DETAILS 1/A103.00 AND 3 AND 4/A104.00. SEE
GENERAL NOTE 10.

2 SOUTH ELEVATION RAKE OUT AND REPOINT (MIN. 3/4" DEPTH) ENTIRE REMAINING FACADE 1,100 SF (APPROX.) PER DETAIL 6/A201.00 WEST ELEVATION

RAKE OUT AND REPOINT (MIN. 3/4" DEPTH) ENTIRE REMAINING FACADE 2,100 SF. (APPROX.). PER DETAIL 6/A201.00

EAST ELEVATION

RAKE OUT AND REPOINT (MIN. 3/4" DEPTH) ENTIRE FACADE 2,300 SF. (APPROX.). PER DETAIL 6/A201.00 CHIMNEY
RAKE OUT AND REPOINT (MIN 3/4" DEPTH) ON THE

INBOARD SIDE OF THE CHIMNEY (40 SFT). PER

EXISTING FIRE ESCAPES TO BE REMOVED AND REPLACED. GC TO PROVIDE SHOP DRAWINGS TO THE STRUCTURAL ENGINEER AND ARCHITECT FOR REVIEW. PATCH AND REPAIR ADJACENT MASONRY

4 EAST ELEVATION

REMOVE, REPLACE AND WATERPROOF EXTERIOR WINDOW LINTELS ONLY (100LF) WITH NEW GALVANIZED STEEL LINTEL. DIMENSIONS TO MATCH EXISTING. SEE DETAIL 1/A201.00.

NORTH ELEVATION

REMOVE, REPLACE AND WATERPROOF EXTERIOR WINDOW LINTELS ONLY (40 LF). INSTALL NEW GALVANIZED STEEL LINTEL INCLUDING ASSOCIATED MASONRY WORK. DIMENSIONS TO MATCH EXISTING. SEE DETAIL 1/A201.00.

SOUTH ELEVATION

REMOVE, REPLACE AND WATERPROOF EXTERIOR
WINDOW LINTELS ONLY (40 LF). INSTALL NEW
GALVANIZED STEEL LINTEL INCLUDING ASSOCIATED
MASONRY WORK. DIMENSIONS TO MATCH EXISTING.
SEE DETAIL 1/A201.00.

WEST ELEVATION
REMOVE, REPLACE AND WATERPROOF EXTERIOR
WINDOW LINTELS ONLY (80 LF). INSTALL NEW
GALVANIZED STEEL LINTEL INCLUDING ASSOCIATE
MASONRY WORK. DIMENSIONS TO MATCH EXISTING.
SEE DETAIL 1/A201.00.

\$\sqrt{5}\ \text{NORTH ELEVATION}

EXISTING STUCCO FINISH TO BE REMOVED DOWN TO SUBSTRATE IN ITS ENTIRETY. ALL OPEN/ERODED MORTAR JOINTS TO BE RAKED OUT AND REPOINTED. PROVIDE NEW STUCCO STO SYSTEM. ASSUMED A TOTAL OF 1000 SF OF STUCCO REPLACEMENT AND 500 SF OF MORTAR JOINT REPOINTING PER DETAILS 5, 5a and 5b/A202.00. SEE GENERAL NOTE 10.

6 NORTH ELEVATION PROVIDE (2) TWO COATS

PROVIDE (2) TWO COATS OF A BREATHABLE ELASTOMERIC COATING (DOW ALLGUARD OR EQUAL) TO THE ENTIRE FACADE. COLOR TO BE SELECTED BY ARCHITECT.

7 THROUGH-WALL FLASHING
PROVIDE 2 PIECE 22 GAUGE STAINLESS
THROUGH-WALL FLASHING AT SOUTH ELEVATION

PER DETAIL 1/A103.00.

B GRANITE PANELS
ALL GRANITE PANELS AT 1ST FLOOR OF THE SOUTH, WEST AND EAST ELEVATIONS TO BE REMOVED AND REPLACED WITH NEW PANELS. SUBMIT SAMPLES AND SHOP DRAWINGS FOR REVIEW. ALL ANCHORS TO BE STAINLESS STEEL TYPE 304. PROVIDE CLOSED-CELL BACKER ROD AND SEALANT DOWSIL 756 SMS TO JOINTS. COLOR TO BE SELECTED BY ARCHITECT. SEE DETAILS 1, 2

AND 3/A-202.00. SEE GENERAL NOTE 10.

SOUTH ELEVATION
EXISTING GRANITE CLADDING AT ENTRANCE
RECESSED VESTIBULE AREA TO BE REMOVED.
PROVIDE STUCCO FINISH PER DETAILS 7, 7a AND
7b/A-201.00. COLOR TO BE SELECTED BY
ARCHITECT. SEE GENERAL NOTE 10.

(9) CHIMNEY PATCH DAMAGED CONCRETE TOP AT CHIMNEY.

NORTH ELEVATION

PATCH & REPAIR EXISTING BRICK PARAPET TO MATCH ADJACENT WHERE EXISTING STEEL DUNNAGE SUPPORTS ARE REMOVED. REFERENCE DETAIL 4/A201.00. SEE GENERAL NOTE 10.

√1) WEST ELEVATION

CRACKED BRICK CONTINGENCY 250 SF, SEE DETAIL 4/A201.00. NEW BRICK MASONRY TO MATCH EXISTING IN ALL RESPECTS.

12 WEST ELEVATION

REMOVE/SEAL EMBEDDED ANCHORS, SEE DETAIL 6/A201.00

WINDOW REPLACEMENT

ALL EXISTING WINDOWS AT THE 2ND FLOOR OF THE NORTH, EAST, WEST AND SOUTH ELEVATIONS TO BE REMOVED DOWN TO MASONRY OPENING AND REPLACED WITH NEW ANDERSEN 400 SERIES WINDOWS. CONTRACTOR TO VERIFY OPENING DIMENSIONS IN FIELD. SEE DETAILS 1, 1A AND 1B/A201.00. PROVIDE WINDOW SHOP DRAWINGS FOR REVIEW.

WEST ELEVATION
PROVIDE SEALANT AT LOUVER PERIMETER.
ASSUME 50 LF.

REMOVE ALL EPDM ROOFING AND FLASHING SYSTEMS DOWN TO EXISTING WOOD DECK, INCLUDING BUT NOT LIMITED TO PENETRATION POCKETS, INSULATION, OTHER MEMBRANES ETC. PROVIDE NEW ROOFING SYSTEM AS SHOWN ON DETAIL A ON A-203.00. REMOVE/REPLACE DAMAGED EXISTING PLYWOOD SHEATHING AS REQUIRED WITH NEW 3/4" THICK WOOD ROOF SHEATHING. ASSUME 50% OF PLYWOOD SHEATHING REPLACEMENT.

PREFABRICATED CURB WITH INSULATED CORE, THYCURB OR APROVED EQUAL. REFER TO DETAIL 9 ON A-203.00.

DISCONNECTED, RAISED AND RECONNECTED. COORDINATE WORK WITH MEP DRAWINGS. PROVIDE PREFABRICATED CURB WITH INSULATED CORE, THYCURB OR APROVED EQUAL. REFER TO DETAIL 9

ON A-203.00.

NEW ROOF EQUIPMENT. PROVIDE PREFABRICATED CURB WITH INSULATED CORE, THYCURB OR APROVED EQUAL. COORDINATE WORK WITH MEP DRAWINGS. REFER TO DETAILS 7 AND 9 ON A-203.00.

18 EXISTING EQUIPMENT CURB TO BE REMOVED.
PROVIDE NEW INSULATED CORE CURB. THYCURB OR
APPROVED EQUAL. FLASH PER DETAIL 9 ON A-203.00.

19 EXISTING ELECTRICAL CONDUITS TO BE TEMPORARILY DISCONNECTED AND RAISED TO ALLOW FOR ROOFING INSTALLATION. REMOVE/ OR REINSTALL CONDUITS AS REQUIRED. COORDINATE WITH MEP DRAWINGS.

20 EXISTING SCUPPERS TO BE REMOVED AND REPLACED. REFER TO DETAIL 6/A-203.00.

Bankof America 🔷

CBRE
Global Corporate Services
Project Management
1133 Avenue of the Americas
New York, NY 10036

Attn: Margaret DiLorenzo


T: 914.299.0078

Gilsanz Murray Steficek LLP
Structure / Building Envelope
129 West 27th Street, 5th Fl.
New York, NY 10001
T: 212.254.0030
Email: Mark.Beltramello@GMSLLP.com
Email: Jonathan.Hernandez@GMSLLP.com

Email: margaret.dilorenzo@cbre.com

Alexander Avenue

Attn: Mark Beltramello / Jonathan Hernandez



11.08.2021 ISSUED FOR LANDLORD COMMENT
10.14.2021 ISSUED FOR LANDLORD COMMENT
07.15.2021 ISSUED FOR PERMIT & PRICING VI
03.24.2021 ISSUED FOR PERMIT & PRICING V
02.03.2021 ISSUED FOR PERMIT & PRICING II
10.12.2020 ISSUED FOR LANDLORD REVIEW
08.18.2020 ISSUED FOR LANDLORD REVIEW
08.07.2020 ISSUED FOR REVIEW
05.12.2020 REVISED

04.27.2020 REVISED

04.13.2020 ISSUED FOR REVIEW

06.25.2019 ISSUED FOR LANDLORD REVIEW

NO DATE REVISIONS



ject:

Bank of America
Facade Repairs and Roof Replacement
928 McLean Avenue,

Drawing Title:
ROOF PLAN

Yonkers, NY 10704


 Project No.:
 Date:


 18581
 06.25.2019

 Drawn By:
 Scale:

 DK
 As Noted

 PAGE 03 OF 09





EXISTING PARAPET EAST ELEVATION (REMOVALS)

SCALE: 1 1/2"=1'-0"

EXISTING PARAPET AT SOUTH ELEVATION (REMOVALS)


SCALE: 1 1/2"=1'-0"

Bankof America 🔷

Global Corporate Services Project Management 1133 Avenue of the Americas New York, NY 10036 T: 914.299.0078 Email: margaret.dilorenzo@cbre.com Attn: Margaret DiLorenzo

Gilsanz Murray Steficek LLP Structure / Building Envelope 129 West 27th Street, 5th Fl. New York, NY 10001 T: 212.254.0030 Email: Mark.Beltramello@GMSLLP.com Email: Jonathan.Hernandez@GMSLLP.com Attn: Mark Beltramello / Jonathan Hernandez

Alexander Avenue



|11.08.2021| ISSUED FOR LANDLORD COMMENTS 10.14.2021 ISSUED FOR LANDLORD COMMENT 07.15.2021 ISSUED FOR PERMIT & PRICING VI 03.24.2021 ISSUED FOR PERMIT & PRICING V 02.03.2021 ISSUED FOR PERMIT & PRICING II 10.12.2020 ISSUED FOR LANDLORD REVIEW 08.18.2020 ISSUED FOR LANDLORD REVIEW

08.07.2020 ISSUED FOR REVIEW 05.12.2020 REVISED 04.27.2020 REVISED

04.13.2020 ISSUED FOR REVIEW 06.25.2019 ISSUED FOR LANDLORD REVIEW NO DATE REVISIONS




Project:
Bank of America

Facade Repairs and Roof Replacement 928 McLean Avenue, Yonkers, NY 10704

Drawing Title: PARAPET SECTIONS REMOVAL WORK

Project No.: Date:
18581 06.25.2019
Drawn By: Scale:
DK As Noted

A-103.00 PAGE 04 OF 09




Bankof America 🔷

Global Corporate Services Project Management 1133 Avenue of the Americas New York, NY 10036 T: 914.299.0078 Email: margaret.dilorenzo@cbre.com Attn: Margaret DiLorenzo

Gilsanz Murray Steficek LLP Structure / Building Envelope 129 West 27th Street, 5th Fl. New York, NY 10001

T: 212.254.0030 Email: Mark.Beltramello@GMSLLP.com Email: Jonathan.Hernandez@GMSLLP.com Attn: Mark Beltramello / Jonathan Hernandez

Alexander Avenue



11.08.2021 ISSUED FOR LANDLORD COMMENTS 10.14.2021 ISSUED FOR LANDLORD COMMENT 07.15.2021 ISSUED FOR PERMIT & PRICING VI 03.24.2021 ISSUED FOR PERMIT & PRICING V 02.03.2021 ISSUED FOR PERMIT & PRICING II 10.12.2020 ISSUED FOR LANDLORD REVIEW 08.18.2020 ISSUED FOR LANDLORD REVIEW 08.07.2020 ISSUED FOR REVIEW 05.12.2020 REVISED

04.27.2020 REVISED 04.13.2020 ISSUED FOR REVIEW 06.25.2019 ISSUED FOR LANDLORD REVIEW NO DATE REVISIONS



Bank of America Facade Repairs and Roof Replacement


928 McLean Avenue, Yonkers, NY 10704 Drawing Title: NEW PARAPET SECTIONS

 Project No.:
 Date:

 18581
 06.25.2019

 Drawn By:
 Scale:

 DK
 As Noted
 A-104.00 PAGE 05 OF 09



Bankof America 🔷

Global Corporate Services Project Management 1133 Avenue of the Americas New York, NY 10036


Attn: Margaret DiLorenzo

T: 914.299.0078

Gilsanz Murray Steficek LLP Structure / Building Envelope 129 West 27th Street, 5th Fl. New York, NY 10001 T: 212.254.0030 Email: Mark.Beltramello@GMSLLP.com Email: Jonathan.Hernandez@GMSLLP.com Attn: Mark Beltramello / Jonathan Hernandez

Email: margaret.dilorenzo@cbre.com

Alexander Avenue



11.08.2021 ISSUED FOR LANDLORD COMMENT 10.14.2021 ISSUED FOR LANDLORD COMMENT 07.15.2021 ISSUED FOR PERMIT & PRICING VI 03.24.2021 ISSUED FOR PERMIT & PRICING V 02.03.2021 ISSUED FOR PERMIT & PRICING II 10.12.2020 ISSUED FOR LANDLORD REVIEW 08.18.2020 ISSUED FOR LANDLORD REVIEW

08.07.2020 ISSUED FOR REVIEW 05.12.2020 REVISED 04.27.2020 REVISED

04.13.2020 ISSUED FOR REVIEW 06.25.2019 ISSUED FOR LANDLORD REVIEW o date revisions

ENGINEERS & ARCHITECTS
129 West 27 Street
New York, New York 10001
212-254-0030, fax.212-477-5978
www.gmsllp.com

GILSANZ.MURRAY.STEFICEK.LLP

Bank of America Facade Repairs and Roof Replacement

928 McLean Avenue, Yonkers, NY 10704 Drawing Title:


DETAILS

 Project No.:
 Date:

 18581
 06.25.20

 Drawn By:
 Scale:
 A-201.00 06.25.2019

PAGE 06 OF 09



NEW GRANITE CLADDING WINDOW SILL DETAIL SCALE: 3"=1'-0"


WINDOW SILL (V.I.F.)


MASONRY SUBSTRATE -

NEW GRANITE CLADDING -

HB #435, 12 GA STAINLESS STEEL TYPE 304 STONE

EXISTING BRICK





STUCCO FISNISH AT HORIZONTAL JOINTS- ISOMETRIC

SCALE: 1 1/2"=1'-0"


Bankof America 🔷

Global Corporate Services Project Management 1133 Avenue of the Americas New York, NY 10036 T: 914.299.0078 Email: margaret.dilorenzo@cbre.com

Attn: Margaret DiLorenzo

Gilsanz Murray Steficek LLP Structure / Building Envelope 129 West 27th Street, 5th Fl. New York, NY 10001 T: 212.254.0030 Email: Mark.Beltramello@GMSLLP.com Email: Jonathan.Hernandez@GMSLLP.com Attn: Mark Beltramello / Jonathan Hernandez

Alexander Avenue



11.08.2021 ISSUED FOR LANDLORD COMMENTS 10.14.2021 ISSUED FOR LANDLORD COMMENT 07.15.2021 ISSUED FOR PERMIT & PRICING VI 03.24.2021 ISSUED FOR PERMIT & PRICING V 02.03.2021 ISSUED FOR PERMIT & PRICING II 10.12.2020 ISSUED FOR LANDLORD REVIEW 08.18.2020 ISSUED FOR LANDLORD REVIEW 08.07.2020 ISSUED FOR REVIEW

05.12.2020 REVISED 04.27.2020 REVISED 04.13.2020 ISSUED FOR REVIEW

06.25.2019 ISSUED FOR LANDLORD REVIEW NO DATE REVISIONS



Project:
Bank of America

Facade Repairs and Roof Replacement 928 McLean Avenue, Yonkers, NY 10704

Drawing Title: NEW PARAPET SECTIONS


A-202.00

 Project No.:
 Date:

 18581
 06.25.2019

 Drawn By:
 Scale:

 DK
 As Noted
 PAGE 07 OF 09



A-203.00

PAGE 08 OF 09



PHOTO No.1: OVERALL VIEW OF SOUTH ELEVATION.

APPLY SEALANT AT LOUVER

PERIMETER -



REFER TO TASK #4/A-101.00

PHOTO No.2: VIEW OF WEST ELEVATION.



- REFER TO TASK #11/A-101.00

PHOTO No.3: OVERALL VIEW OF EAST ELEVATION.





PHOTO No.8: EXISTING CHIMNEY TO REMAIN. PATCH CONCRETE TOP AS




PHOTO No.5: CORRODED/DEFLECTED STEEL WINDOW LINTEL TO BE REMOVED/REPLACED WTH NEW GALVANIZED STEEL LINTEL.



REMOVED/REPLACED WTH NEW GALVANIZED STEEL LINTEL. OPEN/ERODED

PHOTO No.10: MAIN ROOF, LOOKING SOUTH. EXISTING EPDM ROOFING TO BE REMOVED AND REPLACED.



PHOTO No.7: DAMAGED BRICK MASONRY TO BE REMOVED/REPLACED

WITH NEW BRICK TO MATCH EXISTING IN ALL RESPECTS.

PHOTO No.11: MAIN ROOF-LOOKING NORTH. EXISTING EQUIPMENT CURBS TO BE REMOVED AND REPLACED WITH NEW INSULATED CORE CURBS. FLASH PER DETAIL 9/A-203.00.



PHOTO No.12: ROOF EQUIPMENT AT NORTHEAST CORNER TO BE REMOVED AND RELOCATED. STEEL DUNNAGE SUPPORT TO BE REMOVED.



PHOTO No.9: MAIN ROOF, LOOKING SOUTH. EXISTING EPDM ROOFING TO BE

REMOVED AND REPLACED.

PHOTO No.13: ROOF VENT TO REMAIN. FLASH PER DETAIL 2/203.00.



PHOTO No.14: PITCHPOCKET TO BE REMOVED. FLASH PENETRETION PER



PHOTO No.15: SKYLIGHT ASSEMBLY TO BE REFURBISHED.SEE NOTE No.9 ON T-001.00.



PHOTO No.16: ROOF SCUPPER TO BE FLASHED PER DETAIL 6/A-203.00.



Global Corporate Services Project Management
1133 Avenue of the Americas New York, NY 10036 T: 914.299.0078 Email: margaret.dilorenzo@cbre.com Attn: Margaret DiLorenzo

Gilsanz Murray Steficek LLP Structure / Building Envelope 129 West 27th Street, 5th Fl. New York, NY 10001 T: 212.254.0030 Email: Mark.Beltramello@GMSLLP.com Email: Jonathan.Hernandez@GMSLLP.com Attn: Mark Beltramello / Jonathan Hernandez

Alexander Avenue



KEY PLAN Z

11.08.2021 ISSUED FOR LANDLORD COMMENTS

10.14.2021 ISSUED FOR LANDLORD COMMENTS 07.15.2021 ISSUED FOR PERMIT & PRICING VI 03.24.2021 ISSUED FOR PERMIT & PRICING V 02.03.2021 ISSUED FOR PERMIT & PRICING II 10.12.2020 ISSUED FOR LANDLORD REVIEW 08.18.2020 ISSUED FOR LANDLORD REVIEW 08.07.2020 ISSUED FOR REVIEW

05.12.2020 REVISED 04.27.2020 REVISED

04.13.2020 ISSUED FOR REVIEW 06.25.2019 ISSUED FOR LANDLORD REVIEW NO DATE REVISIONS



Project:
Bank of America

Facade Repairs and Roof Replacement 928 McLean Avenue, Yonkers, NY 10704

Drawing Title: CONDITION PHOTOGRAPHS

Project No.: Date:
18581 06.25.2019
Drawn By: Scale:
DK As Noted A-301.00 PAGE 09 OF 09