



REINFORCEMENT SCHEDULE	
R1	#5 BARS @ 10" O.C. VERT. #4 BARS @ 10" O.C. HORIZ.
R2	#5 BARS @ 8" O.C. VERT. #4 BARS @ 12" O.C. HORIZ.
R3	#5 BARS @ 12" O.C. VERT. #4 BARS @ 10" O.C. HORIZ.
R4	#4 BARS @ 12" O.C. VERT. #4 BARS @ 12" O.C. HORIZ.
R5	#5 BARS @ 10" O.C. VERT. #4 BARS @ 12" O.C. HORIZ.
R6	#5 BARS @ 10" O.C. VERT. #4 BARS @ 10" O.C. HORIZ.
R7	#5 BARS @ 12" O.C. VERT. #4 BARS @ 10" O.C. HORIZ.