

City of Peekskill (Owner)
701 Washington Street
Peekskill, New York 10566
S-B-L: 32.20-9-1

S-B-L: 32.20-9-1
City of Peekskill - Westchester County




1. ALL HYDRONIC PIPING IS 1¼" UNLESS OTHERWISE NOTED.
2. REMOVE ALL HYDRONIC PIPING NOT RUN WITHIN WALLS OR UNDER SLAB. CUT BACK PIPES BEHIND THE WALL AND FLOOR, THEN CAP LINES TO ABANDON IN-PLACE. PATCH, SEAL, AND REPAIR WALLS AND FLOORS TO MATCH EXISTING

- ① DEMOLISH PTAC HYDRONIC PIPING BACK TO WALL/FLOOR PENETRATION AND CAP TO ABANDON IN-PLACE. G.C. TO PATCH, SEAL AND REPAIR WALL/FLOOR TO MATCH EXISTING.
- ② CUT AND CAP HYDRONIC PIPING BEHIND WALL/FLOOR PENETRATION. G.C. TO PATCH, SEAL AND REPAIR WALL/FLOOR TO MATCH EXISTING.
- ③ EXISTING FIN TUBE HEATING ELEMENT AND ENCLOSURE TO BE REMOVED. DEMOLISH HYDRONIC PIPING BACK THROUGH WALL/FLOOR AND CAP TO ABANDON IN-PLACE. G.C. TO PATCH, SEAL, AND REPAIR WALL/FLOOR TO MATCH EXISTING.
- ④ SEE DETAIL 1/H7.01 FOR HYDRONIC HEATING PIPING IN THIS AREA.
- ⑤ DEMOLISH HYDRONIC UNIT HEATER. G.C. TO PATCH, SEAL, AND REPAIR WALL/FLOOR TO MATCH EXISTING.

FELLENZER 
ENGINEERING LLP
www.fello.com

DESIGNED BY: RW	DRAWN BY: WBR	APPROVED BY: EDE	FE PROJECT #: 23-36
--------------------	------------------	---------------------	------------------------



Revisions

HD2.01