

1 CONCRETE CEIILING REPAIR DETAIL (LEVEL 1 REPAIR)
SCALE 3" = 1'-0" (NORTH PORTICO ONLY)



2 CONCRETE CEILING REPAIR DETAIL (LEVEL 2 REPAIR)
SCALE 3" = 1'-0" (NORTH PORTICO ONLY)



3 CONCRETE REPAIR DETAIL PLAN VIEW (UNDERSIDE OF DECK)
SCALE 3" = 1'-0" (NORTH PORTICO ONLY)



4 TYPICAL ROOF EXHAUST VENT DETAIL
SCALE 1 1/2" = 1'-0"



5 MASONRY REPAIR DETAIL
SCALE 1" = 1'-0"



6 FLASHING DETAIL AT CHIMNEY AND VERTICAL WALLS
SCALE 3" = 1'-0"



7 VALLEY DETAIL
SCALE 3" = 1'-0"

ADD ALTERNATE NO. GC-1
REFER TO PROJECT MANUAL
SECTION 012300 FOR DESCRIPTION.



8 TYPICAL ROOF PENETRATION DETAIL
SCALE 3" = 1'-0"



9 RIDGE DETAIL
SCALE 3" = 1'-0"



10 ROOF TRANSITION DETAIL
SCALE 3" = 1'-0"



11 RECONSTRUCTED SOFFIT DETAIL
SCALE 1 1/2" = 1'-0"



12 RAKE DETAIL
SCALE 1 1/2" = 1'-0"



13 ROOF DETAIL AT DORMERS
SCALE 3" = 1'-0"



14 SILL DETAIL AT DORMERS
SCALE 3" = 1'-0"



15 TRIM DETAIL
ROOF EDGE DETAIL AT ELEVATOR -

Lothrop

Lothrop Associates LLP Architects
333 Westchester Avenue
White Plains, NewYork 10604
914-741-1115

White Plains Rochester Red Bank Hartford

BLAKE ENGINEERING PLLC
1898 COUNTY ROUTE 1, WESTTOWN, NY 10998
TEL: 845-667-9207 FAX: 845-747-3050
MBLAKE@BLAKEENGINEERINGPLLC.COM

MATTHEW G. BLAKE, P.E. LEED AP
NY - 890329 NJ - GE050037 PA - PE079303
MA - 53197 CT - 32283 FL - 85928

E/M/S
ENVIRONMENTAL MANAGEMENT SOLUTIONS
420 COLUMBUS AVENUE,
VALHALLA, NY 10595

ISSUE NO.	ISSUE DATE	DESCRIPTION
1	03-19-2021	ISSUED FOR BID

REGISTERED ARCHITECT MICHAEL A. BLAKE 032645 STATE OF NEW YORK

ALTERATIONS TO BUILDING # 51, EMERGENCY HOUSING GROUP
38 SEWARD AVENUE
MIDDLETOWN, NY 10940

EXTERIOR BUILDING DETAILS

PROJECT NO.: 1802-01

DRAWING NO.:

A-500

one inch = one foot
three quarters inch = one foot
one half inch = one foot
three eighths inch = one foot
one quarter inch = one foot
one eighth inch = one foot
K:\10 PROJECTS\Government\1802 01 - Orange County - Homeless Shelter\1800 01_Drawings\1800 01_18_1105 - Active Maps\1800_01_18_1105_A500 Details.dwg